ACKNOWLEDGEMENT AND RELEASE

I, the undersigned, have received a copy of a CarFax vehicle history report, a copy of which is attached to this document. The particulars of the vehicle are as follows:

v	/IN:	JM1BL1UF7D1756882
N	Nake:	MAZDA
N	lodel:	MAZDA3
S	Stock No:	MMON103526
R	Report Date:	11/19/2021 10:29:37
H	have read the	e report and understand its contents.
11	hereby releas	se Stark Auto Sales from any disclosure obligations with regard to the information contained in the report.
D	Dated this	day of,
С	Customer's Si	gnature:

Customer's Name: _____



2013 MAZDA 3 I

Sedan | 4 Cylinders | Gas JM1BL1UF7D1756882 Country of Assembly: Japan Last Reported Odometer: 145,000 KM

Accident/Damage Records Found

Last Registered In: Ontario (Salvage)

17 Service Records Found

No U.S. History Found

No Open Recalls Found

Not Actively Declared Stolen

No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca

 (\mathbf{i})

This vehicle history report is based on information that was reported and available to CARFAX Canada as of November 19, 2021 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
1 2020 Sep 13	Kingston, Ontario, Canada	
	Police Reported Accident:	
	Accident reported: minor damage	
	with another motor vehicle	
	Damage to right rear	
	Estimate:	\$1,801.31
	Right Rear Side Estimate Date: 2020 Oct 8	\$1,801.31
	Claim:	\$1,801.00
	Other Damage	\$1,001.00
2021 Jun 9	Kingston, Ontario, Canada	
	Police Reported Accident:	
	Accident reported: severe damage	
	Involving front or side impact	
	with another motor vehicle	
	Damage to left front	
	Estimate:	\$13,254.35
	Total Loss Estimate Date: 2021 Jul 22	C.+C.2,C+C.2
	Claim:	\$4,673.00
	Collision	\$ 4 ,073.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2021 Nov 8	Ontario, Canada	
	Registration Event: Salvage	



Registration

0

This vehicle has been registered in the province of Ontario in Canada with Salvage branding.

SOURCE

Details:

Damaged to the extent that cost of repairing the vehicle for legal operation on the public roads exceeds its fair market value immediately prior to damage. We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE ODOMETER

DETAILS

DATE	ODOMETER	SOURCE	DETAILS		
2014 Jun 25	8,280 KM	Service Facility Toronto, Ontario, Canada	Vehicle serviced		
2014 Aug 28	16,410 KM	Service Facility Toronto, Ontario, Canada	Vehicle serviced		
2014 Nov 14	20,923 KM	Active Green & Ross Etobicoke, Ontario, Canada	Vehicle serviced Maintenance inspection completed Tire condition and pressure checked Tire(s) replaced Four tires balanced Four tires mounted Wheels checked 		
2015 Feb 14	25,164 KM	Service Facility Toronto, Ontario, Canada	Vehicle serviced		
2015 Apr 21	28,782 KM	Active Green & Ross Etobicoke, Ontario, Canada	Vehicle serviced Maintenance inspection completed Tire(s) changed 		
2015 Nov 28	41,450 KM	Active Green & Ross Etobicoke, Ontario, Canada	Vehicle serviced Maintenance inspection completed Tires rotated Tire(s) changed 		
2016 May 6	49,119 KM	Active Green & Ross Etobicoke, Ontario, Canada	Vehicle serviced Maintenance inspection completed Tire(s) changed 		
2016 Dec 5	62,055 KM	Active Green & Ross Etobicoke, Ontario, Canada	Vehicle serviced Maintenance inspection completed Tire(s) changed 		
2017 Jun 12	75,869 KM	Ajax Mazda Ajax, Ontario, Canada	Vehicle serviced 72,000 kilometer service performed 		
2017 Dec 18	84,304 KM	Valvoline Express Care - Whitby Whitby, Ontario, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed 		
2018 Jul 4	89,620 KM	Valvoline Express Care - Whitby Whitby, Ontario, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed 		
2018 Dec 13	95,498 KM	Valvoline Express Care - Whitby Whitby, Ontario, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed 		
2019 May 11	100,827 KM	WHITBY MAZDA Whitby, Ontario, Canada	Vehicle serviced Oil and filter changed Tire condition and pressure checked 		
2019 Jun 25	103,441 KM	WHITBY MAZDA Whitby, Ontario, Canada	Vehicle serviced		
2019 Oct 16	107,981 KM	Mr. Automotive Whitby, Ontario, Canada	Vehicle serviced Safety inspection performed 		
2020 May 29	110,248 KM	Petrie Ford Kingston, Ontario, Canada	Vehicle serviced Pre-delivery inspection completed Wiper(s) replaced 		
2020 Jul 13		Petrie Ford Kingston, Ontario, Canada	Vehicle serviced		



Open Recalls

0

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact MAZDA or visit Mazda's website.




Stolen Vehicle Check

C

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Jan 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	First Owner Reported
2014 Jan 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Jun 25	8,280 KM	Service Facility Toronto, Ontario, Canada	Service Record	Vehicle serviced
2014 Aug 28	16,410 KM	Service Facility Toronto, Ontario, Canada	Service Record	Vehicle serviced
2014 Oct 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Nov 14	20,923 KM	Active Green & Ross Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2015 Feb 14	25,164 KM	Service Facility Toronto, Ontario, Canada	Service Record	Vehicle serviced
2015 Apr 21	28,782 KM	Active Green & Ross Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2015 Oct 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Nov 28	41,450 KM	Active Green & Ross Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2016 May 6	49,119 KM	Active Green & Ross Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2016 Oct 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Dec 5	62,055 KM	Active Green & Ross Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2017 Jun 12	75,869 KM	Ajax Mazda Ajax, Ontario, Canada	Service Record	Vehicle serviced
2017 Oct 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Dec 18	84,304 KM	Valvoline Express Care - Whitby Whitby, Ontario, Canada	Service Record	Vehicle serviced
2018 Jul 4	89,620 KM	Valvoline Express Care - Whitby Whitby, Ontario, Canada	Service Record	Vehicle serviced
2018 Oct 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Dec 13	95,498 KM	Valvoline Express Care - Whitby Whitby, Ontario, Canada	Service Record	Vehicle serviced
2019 May 11	100,827 KM	WHITBY MAZDA Whitby, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 25	103,441 KM	WHITBY MAZDA Whitby, Ontario, Canada	Service Record	Vehicle serviced
2019 Oct 16	107,981 KM	Mr. Automotive Whitby, Ontario, Canada	Service Record	Vehicle serviced

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Nov 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Nov 12		Motor Vehicle Dept. Ontario, Canada	Previous use	Commercial
2020 May 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2020 May 29	110,248 KM	Petrie Ford Kingston, Ontario, Canada	Service Record	Vehicle serviced
2020 Jun 11	110,249 KM	Independent Source Kingston, Ontario, Canada	Odometer reading	
2020 Jul 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2020 Jul 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jul 9		Motor Vehicle Dept. Ontario, Canada	Previous use	Commercial
2020 Jul 13		Petrie Ford Kingston, Ontario, Canada	Service Record	Vehicle serviced
2020 Sep 13		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: • minor damage • with another motor vehide • Damage to right rear
2020 Sep 13		Insurance Records Ontario, Canada		
2020 Sep 13	114,696 KM	Insurance Records Kingston, Ontario, Canada	Estimate Repair	Estimate Date: 10/8/2020 Right Rear Side
2021 Jun 9		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: • severe damage • Involving front or side impact • with another motor vehicle • Damage to left front
2021 Jun 9		Insurance Records Ontario, Canada		
2021 Jun 9	145,000 KM	Insurance Records Kingston, Ontario, Canada	Estimate Repair	Estimate Date: 7/22/2021 Total Loss
2021 Nov 8		Ontario, Canada	Registration Event	Salvage
2021 Nov 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, accident information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but on ersponsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or applications are tradicated strictly on an errors, inaccuracies or approximations, and carefax canada and its source data providers full believer and a low source data providers full believer and and and any error or any information contained within a report, including the accuracy thereof or any dense or large to provide are apport or any information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reports or any information. Other information about your new cales. All chains any careful to history report, so and any careful as bubles reports or any information about so and reso approximate. Setting report, including problems, may not have been reports on about your new cales. All chains and use the reports and use that reforms about providers in a provider is the buble that to shice history report, you agree to be bound by all of the terms and conditions in CARFAX Canada. Conditions of Use

© Copyright 2005 - 2021 CARFAX Canada ULC. All rights reserved.

JM1BL1UF7D1756882