# **ACKNOWLEDGEMENT AND RELEASE**

I, the undersign attached to this	ned, have received a copy of a CarFax vehicle history report, a copy of which is s document.
The particulars	s of the vehicle are as follows:
VIN:	WA18NAF46KA011466
Make:	AUDI
Model:	A4 ALLROAD
Stock No:	MMON121980
Report Date:	2024-04-25 13:57:10
I have read the	e report and understand its contents.
I hereby releas contained in th	se Stark Auto Sales from any disclosure obligations with regard to the information e report.
Dated this	day of,
Customer's Sig	gnature:
Customer's Na	me:

Report Status: Complete



# 2019 AUDI A4 ALLROAD PREMIUM PLUS

Sport utility vehicle | 4 Cylinders | Gas WA18NAF46KA011466 Country of Assembly: Germany Last Reported Odometer: 45,314 KM





Last Registered In: Ontario (Normal)



14 Service Records Found







Not Actively Declared Stolen



No Import Record Found


inspection and test drive, to make an informed decision.

Questions? We're here to help.

Visit us at support.carfax.ca



# **Vehicle History Report**



INCIDENT DATE	DETAILS	AMOUNT
<b>1</b> 2024 Jan 24	Etobicoke, Ontario, Canada	
	Estimate: Total Loss   Estimate Date: 2024 Feb 6	\$18,031.98
① 2024 Feb 4	Etobicoke, Ontario, Canada	
	Estimate: Total Loss   Estimate Date: 2024 Feb 6	\$22,765.42
	Claim: Miscellaneous	\$63,223.00

### Other Damage Records

RECORD DATE	DETAILS	AMOUNT
① 2024 Feb 22	n/a	
	<b>Damage Event:</b> Damage reported: minor damage  Damage to front	



This vehicle has been registered in the province of Ontario in Canada with Normal branding.


We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



### **Service Records**

DATE	ODOMETER	SOURCE	DETAILS	
2019 Jul 10		Volkswagen Audi Midtown Toronto	Vehicle serviced	
		Scarborough, Ontario, Canada	Pre-delivery inspection completed	
2019 Jul 30		Kambio Inc	Vehicle serviced	
		Toronto, Ontario, Canada	<ul> <li>Tire(s) mounted</li> </ul>	
			Tire(s) replaced	
2019 Dec 11	3,529 KM	Kambio Inc	Vehicle serviced	
		Toronto, Ontario, Canada	Tire(s) mounted	
2020 Apr 6		Kambio Inc	Vehicle serviced	
		Toronto, Ontario, Canada	<ul> <li>Tire(s) balanced</li> </ul>	
		· ,	Tire repaired	

8,489 KM 14,008 KM	Kambio Inc Toronto, Ontario, Canada Kambio Inc Toronto, Ontario, Canada	<ul> <li>Tire condition and pressure checked</li> <li>Vehicle serviced</li> <li>Oil and filter changed</li> <li>Vehicle serviced</li> </ul>
14,008 KM	Toronto, Ontario, Canada	Oil and filter changed
	Kambio Inc	
		Vehicle serviced
	Toronto, Ontario, Canada	
17,193 KM	Kambio Inc	Vehicle serviced
	Toronto, Ontario, Canada	Tire(s) balanced
19,150 KM	Kambio Inc	Vehicle serviced
	Toronto, Ontario, Canada	<ul><li>Recommended maintenance performed</li><li>Oil and filter changed</li></ul>
		Cabin air filter replaced/cleaned
23,728 KM	Kambio Inc	Vehicle serviced
	Toronto, Ontario, Canada	Tire(s) balanced
28,532 KM	Kambio Inc	Vehicle serviced
	Toronto, Ontario, Canada	Oil and filter changed
		Tire condition and pressure checked
34,181 KM	Kambio Inc	Vehicle serviced
	Toronto, Ontario, Canada	
36,331 KM	Kambio Inc	Vehicle serviced
	Toronto, Ontario, Canada	Tire(s) balanced
37,942 KM	Kambio Inc	Vehicle serviced
	Toronto, Ontario, Canada	Oil and filter changed
43,259 KM	Kambio Inc	Vehicle serviced
	Toronto, Ontario, Canada	<ul><li>Air filter replaced</li><li>Cabin air filter replaced/cleaned</li></ul>
	19,150 KM 23,728 KM 28,532 KM 34,181 KM 36,331 KM	Toronto, Ontario, Canada  19,150 KM Kambio Inc Toronto, Ontario, Canada  23,728 KM Kambio Inc Toronto, Ontario, Canada  28,532 KM Kambio Inc Toronto, Ontario, Canada  34,181 KM Kambio Inc Toronto, Ontario, Canada  36,331 KM Kambio Inc Toronto, Ontario, Canada  37,942 KM Kambio Inc Toronto, Ontario, Canada  Kambio Inc Toronto, Ontario, Canada  Kambio Inc Toronto, Ontario, Canada



Recall #: 74E3 | PASSENGER OCCUPANT DETECTION SYSTEM (PODS) Recall Date: 2021 Nov 23

#### **Recall Description**

The affected vehicles are equipped with a passenger occupant detection system (also known as Body Sense) in the front passenger seat. On these vehicles, the system is integrated in the seat heating and controls the activation of the front passenger airbag. The seat heating is connected to the Body Sense control unit under the front passenger seat via a wire. If the wire has a contact fault, it may cause the passenger occupant detection system (PODS) to detect a malfunction and switch off the passenger airbag even though the seat may be occupied. As designed, a warning light in the instrument panel comes on together with an acoustic warning sound and an error message is displayed in the instrument cluster. The airbag indicator light shows "passenger airbag off". .In the event of a crash, there would be an increased risk of injury to the occupant seated in the front passenger seat if the passenger airbag is switched off/not working.

#### Remedy

Depending on the seat type, the seat heating mats including the connecting cable or the entire seat cover including the connecting cable will be replaced.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed,



### Stolen Vehicle Check



This vehicle is not actively declared stolen.



### **Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Jul 10		Volkswagen Audi Midtown Toronto Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2019 Jul 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray
2019 Jul 30		Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 Dec 11	3,529 KM	Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2020 Apr 6		Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2020 Jul 2	8,489 KM	Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 25	14,008 KM	Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2021 Apr 12	17,193 KM	Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2021 Jun 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2021 Jun 22	19,150 KM	Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 13	23,728 KM	Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 23		AUDI	Recall	Manufacturer Recall Issued Recall # 74E3
2022 May 26	28,532 KM	Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2022 Nov 23	34,181 KM	Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2023 Apr 4	36,331 KM	Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2023 Jun 25	37,942 KM	Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2023 Dec 16	43,259 KM	Kambio Inc Toronto, Ontario, Canada	Service Record	Vehicle serviced
2024 Jan 24	45,314 KM	Insurance Records Etobicoke, Ontario, Canada	Estimate Repair	Estimate Date: 2024-02-06 Total Loss
2024 Feb 4		Insurance Records Ontario, Canada		
2024 Feb 4		Insurance Records Etobicoke, Ontario, Canada	Estimate Repair	Estimate Date: 2024-02-06 Total Loss
2024 Feb 22			Damage Event	Damage reported: minor damage Damage to front
2024 Mar 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray



### Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

